

ATTENTION RESIDENTS

Public Notice

A potential issue has been brought to our attention concerning the clamps on COPPER pipes leading to the water meters and the risk of potential corrosion.

If left unchecked this could lead to water leaks & damage to your property.



*This is a STEEL clamp
which can lead to
corrosion of COPPER
pipes and possible
leaks*



*This is a BRASS clamp
recommended for all
COPPER pipes.*



*Clamps can be seen either side
of water meter*



*Copper pipe showing
signs of corrosion*

The Clamps are a requirement as per the Electrical Code.

They were not placed on the line by Town Employees and they are not the responsibility of the Town of Maidstone.

If you have any further questions please contact
AWB Plumbing and Heating Ltd (306) 903-7992